

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

| FACTORS | | PROFILES | | | | | | | | | | | | | |
|---------------------------|-------------|----------|---|---|---|---|---|---|---|---|----|--|--|--|--|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | | | | |
| LANDSCAPE POSITION | .1940 | | | | | | | | | | | | | | |
| SLOPE (%) | .1940 | | | | | | | | | | | | | | |
| HORIZON 1 DEPTH | | 0.54 | | | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | scL | | | | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | | | | | |
| HORIZON 2 DEPTH | | | | | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | | | | | |
| HORIZON 3 DEPTH | | | | | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | | | | | |
| HORIZON 4 DEPTH | | | | | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | | | | | |
| SOIL WETNESS | .1942 | | | | | | | | | | | | | | |
| RESTRICTIVE HORIZON | .1944 | | | | | | | | | | | | | | |
| SAPROLITE | .1943/.1956 | | | | | | | | | | | | | | |
| CLASSIFICATION | .1948 | | | | | | | | | | | | | | |
| LONG TERM ACCEPTANCE RATE | .1955 | 15 | | | | | | | | | | | | | |

