


SITE/SOI EVALUATION FOR ON-SITE WASTEWATER


APPLICANT NAME _____

DATE _____

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940	0-25%													
HORIZON 1 DEPTH		0-10"	0-8"	0-22"	0-8"	0-8"	0-8"								
Texture Group	.1941(A)(1)	SL	SL	SL	SL	SL	SL								
Consistence	.1941	VFR													
Structure	.1941(A)(2)	Open													
Mineralogy	.1941(A)(3)	NS/SP													
HORIZON 2 DEPTH		8"	8"		8"	8"	8"								
Texture Group	.1941(A)(1)	SCL	SCL		SCL	CL	SCL								
Consistence	.1941	FR			FR		FR								
Structure	.1941(A)(2)				SBK/G										
Mineralogy	.1941(A)(3)				SS/SP										
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942	0-2"	2-6"	20"	27"	30"									
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	US	US	US	PS	PS									
LONG TERM ACCEPTANCE RATE	.1955				.5	.4	.4								



#1 CHROMA 3 @ 25"



ROAD 50' R/W