


# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L							
SLOPE (%)	.1940	2	2	2							
HORIZON 1 DEPTH		0-12	0-12	0-12							
Texture Group	.1941(A)(1)	SL									
Consistence	.1941	PK									
Structure	.1941(A)(2)	OH									
Mineralogy	.1941(A)(3)	NBP									
HORIZON 2 DEPTH		12-18									
Texture Group	.1941(A)(1)	SL									
Consistence	.1941	PK									
Structure	.1941(A)(2)	OH									
Mineralogy	.1941(A)(3)	SSP									
HORIZON 3 DEPTH		18-30									
Texture Group	.1941(A)(1)	SL-CL									
Consistence	.1941	SPK									
Structure	.1941(A)(2)	SBK									
Mineralogy	.1941(A)(3)	SSP									
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
OIL WETNESS	.1942	32	32	32							
RESTRICTIVE HORIZON	.1944										
APROLITE	.1943/1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RATE	.1955	.43	.4	.4							

S 03°59'37"W 318.08' (Total)  
 50' R/W (Public Dedicated)  
 N 03°59'37"E 318.08' (Total)



Required Property Line Setbacks

Front	Side	Corner	Rear	Nearest Building
35'	10'	20'	25'	10'
50'	25'	105'		

Actual

DATE: 10/20/22

Planning Administrator: [Signature]

#BEDROOMS: 3

DISTRICT: M-40

USE: SFD

FILE PLAN APPROVAL: [Signature]

CUMBERLAND HOMES INC.  
 Lot # 69 (VINEYARD) GREEN