SITE/SC EVALUATION FOR ON-SIT WASTEWATER

APPLICANT NAME

DAT

FACTORS		PROFILES									
	_	1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940 .	4	-								1.
SLOPE (%)	.1940	2	7		1						
HORIZON 1 DEPTH		0-29	0-24								
Texture Group	.1941(A)(1)		32								
Consistence	.1941	Pu	PL								
Structure	.1941(A)(2)	on	66								U _n
	.1941(A)(3)	NEWP	NEAR								Y I'V
HORIZON 2 DEPTH		74-42	24-42								
Texture Group	.1941(A)(1)	sel	SCL								
Consistence		pu	PU								
Structure	.1941(A)(2)	COL	4								
	.1941(A)(3)	1550	6451							1 1	E - 1
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	THE REAL PROPERTY OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO I										
Structure	.1941(A)(2)		,								
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH	T			•							
Texture Group	:1941(A)(1)	1491 114									
Consistence	.1941			ing mit en	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- Joseph SE					
Structure	.1941(A)(2)			and the second second							
Mineralogy			yes sector	g de from legan o la filosomo.		- 41.505					A. 12.
SOIL WETNESS	.1942	364	3604			I summer out					
RESTRICTIVE HORIZON	1944	, ,		the second of the second	- 5	Tr					
SAPROLITE	1943/.1956				j . w ye loon						
CLASSIFICATION	1948					e mang e				3 . 3	
LONG TERM ACCEPTANCE RATE	.1955	.4	.4						-		

