

# SITE/SC" EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
<b>HORIZON 1 DEPTH</b>															
Texture Group	.1941(A)(1)	G-19	G-24												
Consistence	.1941	SL	SL												
Structure	.1941(A)(2)	VR	VR												
Mineralogy	.1941(A)(3)	G	C												
<b>HORIZON 2 DEPTH</b>															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
<b>HORIZON 3 DEPTH</b>															
Texture Group	.1941(A)(1)	SL	SL												
Consistence	.1941	SL	SL												
Structure	.1941(A)(2)	VR	VR												
Mineralogy	.1941(A)(3)	G	C												
<b>HORIZON 4 DEPTH</b>															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	PS	PS												
LONG TERM ACCEPTANCE RATE	.1955	5	5												

G  
C  


---

194