SITE/S[illegible] EVALUATION FOR ON-S[illegible] WASTEWATER

APPLICANT NAME _____ **DA..** _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L							
SLOPE (%)	.1940	5	5	5							
HORIZON 1 DEPTH		0-8	0-8	0-8							
Texture Group	.1941(A)(1)	SL									
Consistence	.1941	FR									
Structure	.1941(A)(2)	GR									
Mineralogy	.1941(A)(3)	NSNP									
HORIZON 2 DEPTH		8-18									
Texture Group	.1941(A)(1)	SCL									
Consistence	.1941	FR									
Structure	.1941(A)(2)	GR									
Mineralogy	.1941(A)(3)	SSNP									
HORIZON 3 DEPTH		18-36									
Texture Group	.1941(A)(1)	SCL									
Consistence	.1941	FR									
Structure	.1941(A)(2)	SBK									
Mineralogy	.1941(A)(3)	SSP									
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	30	24	32	26						
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RATE	.1955	.4	.3	.4	.3						