

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940	L	L												
SLOPE (%)	.1940	2	2												
HORIZON 1 DEPTH		0-8													
TEXTURE GROUP	.1941(A)(1)	SL													
CONSISTENCE	.1941	fr													
STRUCTURE	.1941(A)(2)	GM													
MINERALOGY	.1941(A)(3)	PSNP													
HORIZON 2 DEPTH		8-30													
TEXTURE GROUP	.1941(A)(1)	SL-C													
CONSISTENCE	.1941	2-40% fclm													
STRUCTURE	.1941(A)(2)	AKK													
MINERALOGY	.1941(A)(3)	SP													
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942	18	20	24											
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RANGE	.1955														

SAPROLITE  
+  
MASSIVE  
MEDIUM  
CLAY

• LOSS TO BE EVALUATED WITH P.I.TS

• 4

SAP SYSTEM

38" TRENCH BOTTOM