

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940	L	L												
SLOPE (%)	.1940	2													
HORIZON 1 DEPTH		0-8													
TEXTURE GROUP	.1941(A)(1)	SL													
CONSISTENCE	.1941	ML													
STRUCTURE	.1941(A)(2)	GL													
MINERALOGY	.1941(A)(3)	NSNP													
HORIZON 2 DEPTH		8-30													
TEXTURE GROUP	.1941(A)(1)	SL-C													
CONSISTENCE	.1941	ML PM													
STRUCTURE	.1941(A)(2)	ABCL													
MINERALOGY	.1941(A)(3)	S P													
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942	18	18	18											
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956	20													
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RANGE	.1955														

• LOT TO BE EVALUATED WITH PITS

• 38" TRENCH BOTTOM

.4

SAP. 573