

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L							
SLOPE (%)	.1940	5	5	5							
HORIZON 1 DEPTH		0-8	0-8	0-8							
TEXTURE GROUP	.1941(A)(1)	SL									
CONSISTENCE	.1941	FC									
STRUCTURE	.1941(A)(2)	GK									
MINERALOGY	.1941(A)(3)	NSNP									
HORIZON 2 DEPTH		8-36									
TEXTURE GROUP	.1941(A)(1)	2C-C									
CONSISTENCE	.1941	SL SLFC									
STRUCTURE	.1941(A)(2)	SBK									
MINERALOGY	.1941(A)(3)	SSP									
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942	30	28	30							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955	.35	.35	.35							