

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-18	0-14												
TEXTURE GROUP	.1941(A)(1)	LF	LS												
CONSISTENCE	.1941	JF	OK												
STRUCTURE	.1941(A)(2)	C	C												
MINERALOGY	.1941(A)(3)	NCH	NCH												
HORIZON 2 DEPTH		18-30	14-20												
TEXTURE GROUP	.1941(A)(1)	SC1	SC1												
CONSISTENCE	.1941	F	F												
STRUCTURE	.1941(A)(2)	SK	SK												
MINERALOGY	.1941(A)(3)	SC	SC												
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	IS	IS												
LONG TERM ACCEPTANCE RANGE	.1955	.4	.3												




SITE PLAN APPROVAL

DISTRICT RA30 USE SF1D

#BEDROOMS 3

Date 3-13-02 J. Johnson
Zoning Administrator



Lot #23
Donnibrook

Required Property Line Setbacks

	Minimum	Actual
Front	35'	60'
Side	10'	20'
Corner	—	—
Rear	25'	144'
Nearest Building	10'	—

4x75
18-24

Donnibrook @ Run