

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-42	0-38	0-20"											
TEXTURE GROUP	.1941(A)(1)	SL S	SL	SL/LS											
CONSISTENCE	.1941	VFR	VFR												
STRUCTURE	.1941(A)(2)	G/CR	G/CR												
MINERALOGY	.1941(A)(3)	NS/MP	NS/MP												
HORIZON 2 DEPTH			8" x	20-32'											
TEXTURE GROUP	.1941(A)(1)		PM	SCL											
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 3 DEPTH				32"											
TEXTURE GROUP	.1941(A)(1)			PM											
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	PS	PS	PS											
LONG TERM ACCEPTANCE RANGE	.1955	.65	.65	.6											

RF = LST. WATER @ 30"

LRP REPAIR

1 330' LINE

② 18"-26"

FRENCH DRAW ABOVE HOUSE

