

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-4	0-18	0-11											
TEXTURE GROUP	.1941(A)(1)	SL	SL	SL											
CONSISTENCE	.1941	VLR	VLR	VLR											
STRUCTURE	.1941(A)(2)	C	C	C											
MINERALOGY	.1941(A)(3)	NOF	NOF	NOF											
HORIZON 2 DEPTH		4-76	18-76	11-76											
TEXTURE GROUP	.1941(A)(1)	C	C	C											
CONSISTENCE	.1941	Fr	Fr	Fr											
STRUCTURE	.1941(A)(2)	SBK	SBK	SBK											
MINERALOGY	.1941(A)(3)	SCA	SCA	SLP											
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	PS	PS	PS											
LONG TERM ACCEPTANCE RANGE	.1955	.4	.01	.4											

(3)

