

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-6	0-8"												
TEXTURE GROUP	.1941(A)(1)	SL	SL												
CONSISTENCE	.1941	VFR	VFR												
STRUCTURE	.1941(A)(2)	G	G												
MINERALOGY	.1941(A)(3)	NS/NP	NS/NO												
HORIZON 2 DEPTH		6-12"	8-34"												
TEXTURE GROUP	.1941(A)(1)	C	C												
CONSISTENCE	.1941	FR	FR												
STRUCTURE	.1941(A)(2)	SBK	SBK												
MINERALOGY	.1941(A)(3)	SS/SP	SS/SP												
HORIZON 3 DEPTH			34"												
TEXTURE GROUP	.1941(A)(1)		FR/CR2												
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	PS	PS												
LONG TERM ACCEPTANCE RANGE	.1955	.3	.3												

4 x 100' 15"
 STUB PLUMBING OR
 CALL W/ ANY ?'S

