OUNTY HEALTH DEPARTMEN ENVIRONMENTAL HEALTH SECTION

Nº 15558

OPERATIONS PERMIT

| | 000 |
|--|---|
| Property Location: SR# | New Installation Septic Tank Repairs Nitrification Lin |
| Subdivision Prach Tree | Lot # |
| | Quadrant # |
| Contractor: T-Blown | Registration # |
| Basement with Plumbing: Garage: | |
| Water Supply: Well Public Community | |
| Distance From Well:ft. | |
| Following are the specifications for the sewage disposal systematical systems of the sewage disposal systems of the sewage d | em on above captioned property. |
| | t Carl |
| , , | y to Conv. |
| Size of tank: Septic Tank: Dow gallons Pun | np Tank: 1000 gallons |
| Subsurface No. of 3 exact length of each ditch ft. | width of depth of ditches ft. ditches 1824n. |
| French Drain: Linear feet | |
| PERMIT NO. 19067 Inspected b | by: Environmental Health Specialist |
| | A Later HALL Day |
| Lines Dk / Tinks Dk Need) | Check |