

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH											
TEXTURE GROUP	.1941(A)(1)	B-26									
CONSISTENCE	.1941	SC									
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 2 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955										


1 x 2 w

87 82,
170 35 47 E

S 1°36'22"W

E15

N 80°36'22"E



(47)
0.344
AC
GRANT

(49)
0.34
AC

S 80°36'22"W

1/2 to

#48 CRESTVIEW

CUMBERLAND HOMES

50 x 43 = 65' 11 1/2"

Required Property Line Setbacks

	Minimum	Actual
Front	35	45
Side	10	15
Corner	20	
Rear	25	36
Nearest Building	10	

BEI

1662 CLARK

SITE PLAN APPROVAL

DISTRICT PA-ZDR USE SFD

#BEDROOMS 3

Date 10 Apr 07 CBele
Zoning Administrator

REVISION