

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-12	0-14											
TEXTURE GROUP	.1941(A)(1)	LS	LS											
CONSISTENCE	.1941	VF	VF											
STRUCTURE	.1941(A)(2)	G	G											
MINERALOGY	.1941(A)(3)	NCP	NCP											
HORIZON 2 DEPTH		16-32	14-32											
TEXTURE GROUP	.1941(A)(1)	SC	SC											
CONSISTENCE	.1941	VF	VF											
STRUCTURE	.1941(A)(2)	SBUL	SBUL											
MINERALOGY	.1941(A)(3)	SOX	SOX											
HORIZON 3 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 4 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948	PS	PS											
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4											

4 x 75'

CONV.
REP.

(2)

