

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L							
SLOPE (%)	.1940	2	2	2							
HORIZON 1 DEPTH		0-18	0-18	0-18							
TEXTURE GROUP	.1941(A)(1)	SL									
CONSISTENCE	.1941	FA									
STRUCTURE	.1941(A)(2)	GL									
MINERALOGY	.1941(A)(3)	NSNP									
HORIZON 2 DEPTH		18-24									
TEXTURE GROUP	.1941(A)(1)	SL									
CONSISTENCE	.1941	FA									
STRUCTURE	.1941(A)(2)	GL									
MINERALOGY	.1941(A)(3)	NSNP									
HORIZON 3 DEPTH		24-36									
TEXTURE GROUP	.1941(A)(1)	C-CL									
CONSISTENCE	.1941	SL									
STRUCTURE	.1941(A)(2)	GL									
MINERALOGY	.1941(A)(3)	SSN									
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942	32	36	32							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955	.4	.2	.4							

1=60

Required Property Line Setbacks

Front	Minimum	Actual
TIE LINE	35'	53'
N 07°45'16"E	10'	47'
117.96'	25'	40'
	10'	

BARRY & CHRISTA BREAKWELL
MAP # 2001-93

PLAN AP. HOWE
DISTRICT RA30 USE SED
SOLD ROOMS 3

4-12-02 D. O'Neal
Zoning Admin

