


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-16	0-5											
TEXTURE GROUP	.1941(A)(1)	CS	CS											
CONSISTENCE	.1941	VF	VF											
STRUCTURE	.1941(A)(2)	G	G											
MINERALOGY	.1941(A)(3)	WCV	WCV											
HORIZON 2 DEPTH		16-76	5-76											
TEXTURE GROUP	.1941(A)(1)	SC	SC											
CONSISTENCE	.1941	B	K											
STRUCTURE	.1941(A)(2)	SBK	SBK											
MINERALOGY	.1941(A)(3)	SEP	SEP											
HORIZON 3 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 4 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/ 1956													
CLASSIFICATION	.1948	AS	A											
LONG TERM ACCEPTANCE RANGE	.1955	1-3	3											


 ① ②