

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-6"	0-24"	0-8"										
TEXTURE GROUP	.1941(A)(1)	SL	S	S										
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 2 DEPTH		6"-22"	24"	8-72"										
TEXTURE GROUP	.1941(A)(1)	SC2	PM	SC2										
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 3 DEPTH		22"												
TEXTURE GROUP	.1941(A)(1)	SC2												
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 4 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
SOIL WETNESS	.1942	26"	10-18"	30"										
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/1956													
CLASSIFICATION	.1948	PS	US	PS										
LONG TERM ACCEPTANCE RANGE	.1955	19.35		.4										

350'
~~4x85'~~
 4x85'
 12"-14"
 NEED COVER
 LPP REPAIR