

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		C-24	C-24								
TEXTURE GROUP	.1941(A)(1)	SC	SC								
CONSISTENCE	.1941	VH	VH								
STRUCTURE	.1941(A)(2)	C	C								
MINERALOGY	.1941(A)(3)	Wup	Nup								
HORIZON 2 DEPTH		24-26	24-26								
TEXTURE GROUP	.1941(A)(1)	SC	SC								
CONSISTENCE	.1941	H	H								
STRUCTURE	.1941(A)(2)	SB	SB								
MINERALOGY	.1941(A)(3)	SC	SC								
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	AS	AS								
LONG TERM ACCEPTANCE RANGE	.1955	C	SC								

②

