

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		6-28	6-74												
TEXTURE GROUP	.1941(A)(1)	LS	LS												
CONSISTENCE	.1941	VF	VF												
STRUCTURE	.1941(A)(2)	G	G												
MINERALOGY	.1941(A)(3)	MLP	NLP												
HORIZON 2 DEPTH		28-56													
TEXTURE GROUP	.1941(A)(1)	SC													
CONSISTENCE	.1941	G													
STRUCTURE	.1941(A)(2)	SBK													
MINERALOGY	.1941(A)(3)	MLP													
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	PS	PS												
LONG TERM ACCEPTANCE RANGE	.1955	.4	.8												

