

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-11"	0-12"												
TEXTURE GROUP	.1941(A)(1)	S	S												
CONSISTENCE	.1941	VFR	VFR												
STRUCTURE	.1941(A)(2)	CR/C													
MINERALOGY	.1941(A)(3)	NS/NP													
HORIZON 2 DEPTH		11-21"	12-24"												
TEXTURE GROUP	.1941(A)(1)	SL	SL												
CONSISTENCE	.1941	VFR													
STRUCTURE	.1941(A)(2)	CR													
MINERALOGY	.1941(A)(3)	NS/NP													
HORIZON 3 DEPTH		21"+	24"												
TEXTURE GROUP	.1941(A)(1)	SL	SL												
CONSISTENCE	.1941	VFR													
STRUCTURE	.1941(A)(2)	CR													
MINERALOGY	.1941(A)(3)	NS/NP													
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	S	S												
LONG TERM ACCEPTANCE RANGE	.1955	.6	.8												

3 BOR

EVALUATED
BY
PKS

3x70' (AS REQUESTED BY HOMEOWNER)

~~24~~ 32"