

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-14	0-16	0-18										
TEXTURE GROUP	.1941(A)(1)	LS	LS	LS										
CONSISTENCE	.1941	VH	VH	VH										
STRUCTURE	.1941(A)(2)	C	C	C										
MINERALOGY	.1941(A)(3)	NM	NM	NM										
HORIZON 2 DEPTH		14-36	16-36	17-34										
TEXTURE GROUP	.1941(A)(1)	SC1	SC1	SC1										
CONSISTENCE	.1941	F	F	F										
STRUCTURE	.1941(A)(2)	SBC	SBC	SBC										
MINERALOGY	.1941(A)(3)	SC	SC	SC										
HORIZON 3 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 4 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948	PS	PS	PS										
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4	.4										

