


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		6.40									
TEXTURE GROUP	.1941(A)(1)	SC2									
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 2 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943, 1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955	1.5									

1 x 240
18-30

1" = 30'



Lot # 59 Coastview Estates
 Wm Kent Packer Inc.

SITE PLAN APPROVAL

DISTRICT RA-20R USE SFO

#BEDROOMS 3

Date 24 Sept 02 CP
 Zoning Administrator

Required Property Line Setbacks

	Minimum	Actual
Front	<u>35</u>	<u>45</u>
Side	<u>10</u>	<u>15</u>
Corner	<u>20</u>	<u>—</u>
Rear	<u>25</u>	<u>65</u>
Nearest Building	<u>10</u>	<u>—</u>