


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-42													
TEXTURE GROUP	.1941(A)(1)	SCC													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 2 DEPTH		42-48													
TEXTURE GROUP	.1941(A)(1)	S.													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RANGE	.1955	.4													



 L. J. ... 4

 1 x 300

 18-20

SITE PLAN APPROVAL

DISTRICT RAZOR USE SFD


#BEDROOMS 3

Date 6-26-02

Theresa...
Zoning Administrator

Required Property Line Setbacks = 30'

	Minimum	Actual
Front	<u>35</u>	<u>45</u>
Side	<u>10</u>	<u>30</u>
Corner	<u>20</u>	<u>1</u>
Rear	<u>25</u>	<u>40</u>
Nearest Building	<u>10</u>	<u>1</u>



12300
18.2K

Order to show...