

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

| FACTORS | | PROFILES | | | | | | | | | |
|----------------------------|-------------|-----------------|---------------------|---|---|---|---|---|---|---|----|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| LANDSCAPE POSITION | .1940 | | | | | | | | | | |
| SLOPE (%) | .1940 | | | | | | | | | | |
| HORIZON 1 DEPTH | | | | | | | | | | | |
| TEXTURE GROUP | .1941(A)(1) | 0-12 | 0-6 | | | | | | | | |
| CONSISTENCE | .1941 | LS | LS | | | | | | | | |
| STRUCTURE | .1941(A)(2) | ✓K _r | ✓E _r | | | | | | | | |
| MINERALOGY | .1941(A)(3) | C | C | | | | | | | | |
| HORIZON 2 DEPTH | | | | | | | | | | | |
| TEXTURE GROUP | .1941(A)(1) | 12-30 | 0-30 | | | | | | | | |
| CONSISTENCE | .1941 | SC | C | | | | | | | | |
| STRUCTURE | .1941(A)(2) | R _i | E _i | | | | | | | | |
| MINERALOGY | .1941(A)(3) | SB ₂ | SB ₁ /NA | | | | | | | | |
| HORIZON 3 DEPTH | | SO ₁ | SO ₁ | | | | | | | | |
| TEXTURE GROUP | .1941(A)(1) | | | | | | | | | | |
| CONSISTENCE | .1941 | | | | | | | | | | |
| STRUCTURE | .1941(A)(2) | | | | | | | | | | |
| MINERALOGY | .1941(A)(3) | | | | | | | | | | |
| HORIZON 4 DEPTH | | | | | | | | | | | |
| TEXTURE GROUP | .1941(A)(1) | | | | | | | | | | |
| CONSISTENCE | .1941 | | | | | | | | | | |
| STRUCTURE | .1941(A)(2) | | | | | | | | | | |
| MINERALOGY | .1941(A)(3) | | | | | | | | | | |
| SOIL WETNESS | .1942 | | | | | | | | | | |
| RESTRICTIVE HORIZON | .1944 | | | | | | | | | | |
| SAPROLITE | .1943/.1956 | | | | | | | | | | |
| CLASSIFICATION | .1948 | | | | | | | | | | |
| LONG TERM ACCEPTANCE RANGE | .1955 | 1.5 | 1.5 | | | | | | | | |
| | | 1.3 | 1.3 | | | | | | | | |



