

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-3	0-30											
TEXTURE GROUP	.1941(A)(1)	SL	C											
CONSISTENCE	.1941	VP	F											
STRUCTURE	.1941(A)(2)	C	SPK											
MINERALOGY	.1941(A)(3)	NU4	SCP											
HORIZON 2 DEPTH		7-16	0-6											
TEXTURE GROUP	.1941(A)(1)	C	SAD											
CONSISTENCE	.1941	F												
STRUCTURE	.1941(A)(2)	SB												
MINERALOGY	.1941(A)(3)	SCP												
HORIZON 3 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 4 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948	PS	PS											
LONG TERM ACCEPTANCE RANGE	.1955	.7	.7											



4 X 600
18-14