

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-2"		0-2"							
TEXTURE GROUP	.1941(A)(1)	SLC	PM	SLC							
CONSISTENCE	.1941	FR									
STRUCTURE	.1941(A)(2)	SB L	M								
MINERALOGY	.1941(A)(3)	ss/sd									
HORIZON 2 DEPTH		4"-8"		4-6"							
TEXTURE GROUP	.1941(A)(1)	CL		CL							
CONSISTENCE	.1941	FR									
STRUCTURE	.1941(A)(2)	SB K									
MINERALOGY	.1941(A)(3)	ss/sd									
HORIZON 3 DEPTH		8"-36"		8-36"							
TEXTURE GROUP	.1941(A)(1)	C		C							
CONSISTENCE	.1941	SB K									
STRUCTURE	.1941(A)(2)	FR									
MINERALOGY	.1941(A)(3)	S/P									
HORIZON 4 DEPTH		36"		36"							
TEXTURE GROUP	.1941(A)(1)	PM		PM							
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)			M							
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948	PS	US	PS							
LONG TERM ACCEPTANCE RANGE	.1955	.3		.3							

EVALUATED BY PHS

