

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-48													
TEXTURE GROUP	.1941(A)(1)	SC1													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 2 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RANGE	.1955	15													

YDR = 320

S 80°36'22"W

# CRESTHA

N 80°36'22"E

100.00'

100.00'

100.00'

48  
0.344  
AC.

150.00'

150.00'

100.00'

100.00'

100.00'

S 80°36'22"W

28h  
482  
18.33  
1x322

3/5/10  
3/22  
4/5/10  
4/5/10  
5/10/10

Required Property Line Setbacks

Actual	Minimum	Front	Side	Corner	Rear	Nearest Building
50	25	10	10	20	25	10
70	10	10	10	20	25	10
63	25	10	10	20	25	10

SITE PLAN APPROVAL

DISTRICT R-COR USE 5FD

#BEDROOMS 4

Zoning Administrator Abel

Date 2/6/10

CUMBERLAND HOMES INC  
#49 CRESTVIEW  
CREST AVE DRIVE