


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS	PROFILES									
	1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH	0-2	0-4								
TEXTURE GROUP	.1941(A)(1)	C	C							
CONSISTENCE	.1941	VK	VK							
STRUCTURE	.1941(A)(2)	Cn	C							
MINERALOGY	.1941(A)(3)	N GP	NOV							
HORIZON 2 DEPTH		0-7.5	0-30							
TEXTURE GROUP	.1941(A)(1)	C	C							
CONSISTENCE	.1941	F	F							
STRUCTURE	.1941(A)(2)	AK	AK							
MINERALOGY	.1941(A)(3)	SOH	SOH							
HORIZON 3 DEPTH										
TEXTURE GROUP	.1941(A)(1)									
CONSISTENCE	.1941									
STRUCTURE	.1941(A)(2)									
MINERALOGY	.1941(A)(3)									
HORIZON 4 DEPTH										
TEXTURE GROUP	.1941(A)(1)									
CONSISTENCE	.1941									
STRUCTURE	.1941(A)(2)									
MINERALOGY	.1941(A)(3)									
SOIL WETNESS	.1942									
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/.1956									
CLASSIFICATION	.1948									
LONG TERM ACCEPTANCE RANGE	.1955									
		15	15							
		3	3							



Required Property Line Setbacks


	Minimum	Actual
Front	35	40
Side	10	20
Corner	20	20
Rear	25	290
Nearest Building	10	

SITE PLAN APPROVAL

DISTRICT RA30 USE SFD


#BEDROOMS 3

Date 9-11-02 *Theresa Jones*
Zoning Administrator



RPRISES
66
PMENT

1/2" dia



1 x 400
St. 24 - 1/2"