


# SITE/SOIL EVALUATION, JR ON-SITE WASTE...ER

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0.4y												
TEXTURE GROUP	.1941(A)(1)	SCC												
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 2 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 3 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 4 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/1956													
CLASSIFICATION	.1948													
LONG TERM ACCEPTANCE RANGE	.1955	.5												

L7AR  
-5

4x60  
18.24

1" = 30'



**SITE PLAN APPROVAL**  
 DISTRICT R170R USE SF1  
 #BEDROOMS 3  
 Date 9-12-02  
 Zoning Administrator [Signature]

Required Property Line Setbacks	Minimum	Actual
Front	35'	45'
Side	10'	20'
Corner	10'	20'
Rear	25'	63'
Nearest Building	10'	10'

HURFF CONSTRUCTION  
 66 CRESTVIEW  
 .35 AC