

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-24	0-8	0-27											
TEXTURE GROUP	.1941(A)(1)	LS	LS	LS											
CONSISTENCE	.1941	VH	VH	VH											
STRUCTURE	.1941(A)(2)	G	G	G											
MINERALOGY	.1941(A)(3)	WCH	WCH	NCH											
HORIZON 2 DEPTH		24-34	8-24	27-30											
TEXTURE GROUP	.1941(A)(1)	SC	CI	SCI											
CONSISTENCE	.1941	F	F	F											
STRUCTURE	.1941(A)(2)	SBC	SBC	SBC											
MINERALOGY	.1941(A)(3)	SH	SH	SH											
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	PS	PS	PS											
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4	.5											

