

SITE/SOIL EVALUATION FOR ON-SITE WASTE WATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		C-24	C-22	C-20											
TEXTURE GROUP	.1941(A)(1)	LS	LS	LS											
CONSISTENCE	.1941	VF	VF	VF											
STRUCTURE	.1941(A)(2)	G	G	G											
MINERALOGY	.1941(A)(3)	NG1	NG1	NG6											
HORIZON 2 DEPTH		24-36	24-34												
TEXTURE GROUP	.1941(A)(1)	SC1	SC1												
CONSISTENCE	.1941	FC	F												
STRUCTURE	.1941(A)(2)	SD4	SD4												
MINERALOGY	.1941(A)(3)	SC1	SC1												
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	1S	1S	1S											
LONG TERM ACCEPTANCE RANGE	.1955	.5	.4	.8											

