

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-36	0-48												
TEXTURE GROUP	.1941(A)(1)	SL	SL												
CONSISTENCE	.1941	VFR	VFR												
STRUCTURE	.1941(A)(2)	G	G												
MINERALOGY	.1941(A)(3)	NS/NP	NS/NP												
HORIZON 2 DEPTH		36"													
TEXTURE GROUP	.1941(A)(1)	~SCL PM													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)	—													
MINERALOGY	.1941(A)(3)														
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	P3	P3												
LONG TERM ACCEPTANCE RANGE	.1955	.8	.8												

