


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-14	0-12	0-8							
TEXTURE GROUP	.1941(A)(1)	SL	SL	SL							
CONSISTENCE	.1941	UFR	UFR	UFR							
STRUCTURE	.1941(A)(2)	G	G	G							
MINERALOGY	.1941(A)(3)	NCH	NCH	NCH							
HORIZON 2 DEPTH		14-32	12-34	8-30							
TEXTURE GROUP	.1941(A)(1)	SC1	SC1	SC							
CONSISTENCE	.1941	FR	FR	F							
STRUCTURE	.1941(A)(2)	SBC	SBC	SBC							
MINERALOGY	.1941(A)(3)	SCH	SCH	SCH							
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948	P5	P5	P5							
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4	.3							



①

②

③