

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L							
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-12	0-10	0-12							
TEXTURE GROUP	.1941(A)(1)	SL-SC	SL	SL							
CONSISTENCE	.1941	FK	FK								
STRUCTURE	.1941(A)(2)	GR	GR								
MINERALOGY	.1941(A)(3)	SSSP	MSNP								
HORIZON 2 DEPTH			10-18								
TEXTURE GROUP	.1941(A)(1)		SC	U	U						
CONSISTENCE	.1941		KN								
STRUCTURE	.1941(A)(2)		GR								
MINERALOGY	.1941(A)(3)		MSNP								
HORIZON 3 DEPTH			18-28								
TEXTURE GROUP	.1941(A)(1)		SL-CL								
CONSISTENCE	.1941		SLPK								
STRUCTURE	.1941(A)(2)		SBC								
MINERALOGY	.1941(A)(3)		SSSP								
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942	4"	30	30	30						
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955	—	.4	.4	.4						

* Front YARD Chrome mottles for about 4" down
 NOT 6lyede just soil wetness.
 NO Repair IN FRONT

*