

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-12	0-24												
TEXTURE GROUP	.1941(A)(1)	SL	LS												
CONSISTENCE	.1941	VF2	VF2												
STRUCTURE	.1941(A)(2)	G	G												
MINERALOGY	.1941(A)(3)	NS/NP	NS/NP												
HORIZON 2 DEPTH		12-19"	24-28"												
TEXTURE GROUP	.1941(A)(1)	SL	C												
CONSISTENCE	.1941	VF2	FR												
STRUCTURE	.1941(A)(2)	SBK	SBK												
MINERALOGY	.1941(A)(3)	SS/SP	SS/SP												
HORIZON 3 DEPTH		19"-38"	40"												
TEXTURE GROUP	.1941(A)(1)	C	PM												
CONSISTENCE	.1941	FR													
STRUCTURE	.1941(A)(2)	SBK													
MINERALOGY	.1941(A)(3)	SL													
HORIZON 4 DEPTH		38"													
TEXTURE GROUP	.1941(A)(1)	PM 50%													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	P5	P5												
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4												

4 x 75' e 24"

