

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-2"	0-7"												
TEXTURE GROUP	.1941(A)(1)	SL	SL												
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 2 DEPTH		6-18"	7-24"												
TEXTURE GROUP	.1941(A)(1)	SCL	SL												
CONSISTENCE	.1941		VFE												
STRUCTURE	.1941(A)(2)		SBK/CL												
MINERALOGY	.1941(A)(3)		S/SK												
HORIZON 3 DEPTH		18-48"	24-48"												
TEXTURE GROUP	.1941(A)(1)	SLC	SLC												
CONSISTENCE	.1941	FR	FR												
STRUCTURE	.1941(A)(2)	SBK	SBK												
MINERALOGY	.1941(A)(3)	S/S	S/S												
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	PS	PS												
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4												

EVALUATED BY PTG

COBBLES TO B1 HORIZON

4x75'

