

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-7"	0-6"												
TEXTURE GROUP	.1941(A)(1)	SL	SL												
CONSISTENCE	.1941	FR	FR												
STRUCTURE	.1941(A)(2)	CR	CR												
MINERALOGY	.1941(A)(3)	NS NP	NS NP												
HORIZON 2 DEPTH		7-31"	7"-28"												
TEXTURE GROUP	.1941(A)(1)	C	C												
CONSISTENCE	.1941	FR	FR												
STRUCTURE	.1941(A)(2)	SRK	SRK												
MINERALOGY	.1941(A)(3)	S/P	S/P												
HORIZON 3 DEPTH		31"	28"												
TEXTURE GROUP	.1941(A)(1)	PM													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942	31"	28"												
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	PS	PS												
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4												

1 x 300'

