

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-48						0-24						
TEXTURE GROUP	.1941(A)(1)	scl						scl						
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 2 DEPTH								24-30						
TEXTURE GROUP	.1941(A)(1)							sc						
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 3 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 4 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944									26'				
SAPROLITE	.1943, 1956													
CLASSIFICATION	.1948													
LONG TERM ACCEPTANCE RANGE	.1955	5								LPP				

$$\begin{array}{r} 10 \\ \hline 3 \rightarrow 10 \\ \hline 7 \\ \hline 3 \rightarrow 10 \\ \hline 7 \\ \hline 3 \rightarrow 8 \\ \hline 5 \\ \hline 150 \end{array}$$



