

SITE/SOIL EVALUATION FOR ON-SITE WASTE WATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-18													
TEXTURE GROUP	.1941(A)(1)	LS													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 2 DEPTH		18-38													
TEXTURE GROUP	.1941(A)(1)	SCL													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 3 DEPTH		38-4													
TEXTURE GROUP	.1941(A)(1)	SL													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943, 1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RANGE	.1955	.5													

Pump to
the rear
Move house
Back approx 30' & Pump may not
Be Required