

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-10	0-8												
TEXTURE GROUP	.1941(A)(1)	LS	LS												
CONSISTENCE	.1941	VFR	VFR												
STRUCTURE	.1941(A)(2)	G	G												
MINERALOGY	.1941(A)(3)	NS/CP	NS/CP												
HORIZON 2 DEPTH		10" +	8" +												
TEXTURE GROUP	.1941(A)(1)	SCL	SCL												
CONSISTENCE	.1941	VFR	VFR												
STRUCTURE	.1941(A)(2)	SBK/CP	SBK/CP												
MINERALOGY	.1941(A)(3)	NS/CP	NS/CP												
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942		W6'												
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	PS	PS												
LONG TERM ACCEPTANCE RANGE	.1955	.5	.5												

3 x 80'

CONV.
RCP.

