SITE/SOIL EVALU[illegible]TION FOR ON-SITE W[illegible]TEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L							
SLOPE (%)	.1940	4	5	4							
HORIZON 1 DEPTH		0-36									
TEXTURE GROUP	.1941(A)(1)	SL									
CONSISTENCE	.1941	FR									
STRUCTURE	.1941(A)(2)	GR									
MINERALOGY	.1941(A)(3)	MSNP									
HORIZON 2 DEPTH		36-48									
TEXTURE GROUP	.1941(A)(1)	SCL									
CONSISTENCE	.1941	FRI									
STRUCTURE	.1941(A)(2)	GR-SBK									
MINERALOGY	.1941(A)(3)	SSP									
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942	42	42	42							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955	.5	.5	5							