# SITE/SOIL EVALU[illegible]TION FOR ON-SITE W[illegible]TEWATER

| FACTORS | | PROFILES | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| LANDSCAPE POSITION | .1940 | L | L | L | | | | | | | |
| SLOPE (%) | .1940 | 0-18 | 2 | | | | | | | | |
| HORIZON 1 DEPTH | | SL | 0-18 | | | | | | | | |
| TEXTURE GROUP | .1941(A)(1) | FR | SL | | | | | | | | |
| CONSISTENCE | .1941 | GR | FR | | | | | | | | |
| STRUCTURE | .1941(A)(2) | NSNP | GR | | | | | | | | |
| MINERALOGY | .1941(A)(3) | 18-30 | NSNP | | | | | | | | |
| HORIZON 2 DEPTH | | SCL | 18-42 | | | | | | | | |
| TEXTURE GROUP | .1941(A)(1) | SL FRM | SCL | | | | | | | | |
| CONSISTENCE | .1941 | SBK | SL FRM | | | | | | | | |
| STRUCTURE | .1941(A)(2) | S.P | SBK | | | | | | | | |
| MINERALOGY | .1941(A)(3) | | S.P | | | | | | | | |
| HORIZON 3 DEPTH | | | | | | | | | | | |
| TEXTURE GROUP | .1941(A)(1) | | | | | | | | | | |
| CONSISTENCE | .1941 | | | | | | | | | | |
| STRUCTURE | .1941(A)(2) | | | | | | | | | | |
| MINERALOGY | .1941(A)(3) | | | | | | | | | | |
| HORIZON 4 DEPTH | | | | | | | | | | | |
| TEXTURE GROUP | .1941(A)(1) | | | | | | | | | | |
| CONSISTENCE | .1941 | | | | | | | | | | |
| STRUCTURE | .1941(A)(2) | | | | | | | | | | |
| MINERALOGY | .1941(A)(3) | | | | | | | | | | |
| SOIL WETNESS | .1942 | 54 | 54 | 54 | | | | | | | |
| RESTRICTIVE HORIZON | .1944 | | | | | | | | | | |
| SAPROLITE | .1943/.1956 | | | | | | | | | | |
| CLASSIFICATION | .1948 | | | | | | | | | | |
| LONG TERM ACCEPTANCE RANGE | .1955 | .4 | .4 | .4 | | | | | | | |