

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER


FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-48	—————→											
TEXTURE GROUP	.1941(A)(1)	sc												
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 2 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 3 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 4 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948													
LONG TERM ACCEPTANCE RANGE	.1955	.5	—————→											


1x240

18-24

Zoning Administrator
 Date
 11-13-02
 #BEDROOMS
 DISTRICT USE
 SITE PLAN APPROVAL
 R/R/VE
 SFD

Permit copy
 1" = 40'
 CUMBERLAND HOMES
 Lot # 75 (RESTVIEW)





NOTE
 If Plumber's
 IS Satisfied
 And Satisfied
 Where
 Spout may
 Pump Be
 Not Be
 Required
 Mover or
 Mover

1x240
 1x240