

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER


APPLICANT NAME _____

FACTORS		PROFILES										
		1	2	3	4	5	6	7	8	9	10	
LANDSCAPE POSITION	.1940											
SLOPE (%)	.1940											
HORIZON 1 DEPTH		17.40	—————									
Texture Group	.1941(A)(1)	SC										
Consistence	.1941											
Structure	.1941(A)(2)											
Mineralogy	.1941(A)(3)											
HORIZON 2 DEPTH												
Texture Group	.1941(A)(1)											
Consistence	.1941											
Structure	.1941(A)(2)											
Mineralogy	.1941(A)(3)											
HORIZON 3 DEPTH												
Texture Group	.1941(A)(1)											
Consistence	.1941											
Structure	.1941(A)(2)											
Mineralogy	.1941(A)(3)											
HORIZON 4 DEPTH												
Texture Group	.1941(A)(1)											
Consistence	.1941											
Structure	.1941(A)(2)											
Mineralogy	.1941(A)(3)											
SOIL WETNESS	.1942											
RESTRICTIVE HORIZON	.1944											
SAPROLITE	.1943/.1956											
CLASSIFICATION	.1948											
LONG TERM ACCEPTANCE RATE	.1955	.5	—————									

3x80

Lot # 113
Crestwood Estates Phase III
Older Remnants 2001

SITE PLAN APPROVAL
DISTRICT USE RAVOK
#BEDROOMS 3
Date 12-3-07
Zoning Administrator [Signature]



1-90