SITE/SOIL EVALUA..ON FOR ON-SITE WAS.._NATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L							
SLOPE (%)	.1940	2	3	3							
HORIZON 1 DEPTH		0-18									
TEXTURE GROUP	.1941(A)(1)	SL									
CONSISTENCE	.1941	FR									
STRUCTURE	.1941(A)(2)	GR									
MINERALOGY	.1941(A)(3)	NSNP									
HORIZON 2 DEPTH		18-24									
TEXTURE GROUP	.1941(A)(1)	SCL	11	11							
CONSISTENCE	.1941	FR									
STRUCTURE	.1941(A)(2)	GR SBK									
MINERALOGY	.1941(A)(3)	SSSP									
HORIZON 3 DEPTH		24-40									
TEXTURE GROUP	.1941(A)(1)	SC-C									
CONSISTENCE	.1941	SL FR SS									
STRUCTURE	.1941(A)(2)	SBK									
MINERALOGY	.1941(A)(3)	SSSP									
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942	36	36	36							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955	.4	-4	.4							