

# SITE/S . EVALUATION FOR ON-S WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

| FACTORS                   |             | PROFILES |      |   |   |   |   |   |   |   |    |  |  |  |
|---------------------------|-------------|----------|------|---|---|---|---|---|---|---|----|--|--|--|
|                           |             | 1        | 2    | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |  |  |  |
| LANDSCAPE POSITION        | .1940       |          |      |   |   |   |   |   |   |   |    |  |  |  |
| SLOPE (%)                 | .1940       |          |      |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 1 DEPTH           |             | 0-40     | 0-40 |   |   |   |   |   |   |   |    |  |  |  |
| Texture Group             | .1941(A)(1) | LS       | LS   |   |   |   |   |   |   |   |    |  |  |  |
| Consistence               | .1941       | VH       | VH   |   |   |   |   |   |   |   |    |  |  |  |
| Structure                 | .1941(A)(2) | G        | G    |   |   |   |   |   |   |   |    |  |  |  |
| Mineralogy                | .1941(A)(3) | NGH      | NGP  |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 2 DEPTH           |             |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Texture Group             | .1941(A)(1) |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Consistence               | .1941       |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Structure                 | .1941(A)(2) |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Mineralogy                | .1941(A)(3) |          |      |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 3 DEPTH           |             |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Texture Group             | .1941(A)(1) |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Consistence               | .1941       |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Structure                 | .1941(A)(2) |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Mineralogy                | .1941(A)(3) |          |      |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 4 DEPTH           |             |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Texture Group             | .1941(A)(1) |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Consistence               | .1941       |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Structure                 | .1941(A)(2) |          |      |   |   |   |   |   |   |   |    |  |  |  |
| Mineralogy                | .1941(A)(3) |          |      |   |   |   |   |   |   |   |    |  |  |  |
| SOIL WETNESS              | .1942       |          |      |   |   |   |   |   |   |   |    |  |  |  |
| RESTRICTIVE HORIZON       | .1944       |          |      |   |   |   |   |   |   |   |    |  |  |  |
| SAPROLITE                 | .1943/.1956 |          |      |   |   |   |   |   |   |   |    |  |  |  |
| CLASSIFICATION            | .1948       | S        | S    |   |   |   |   |   |   |   |    |  |  |  |
| LONG TERM ACCEPTANCE RATE | .1955       | f        | f    |   |   |   |   |   |   |   |    |  |  |  |

4      ②  
