

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940	L	L	L											
SLOPE (%)	.1940	2	2	2											
HORIZON 1 DEPTH		0-8	0-8	0-10											
Texture Group	.1941(A)(1)	SL	SL	SL											
Consistence	.1941	FL													
Structure	.1941(A)(2)	GL													
Mineralogy	.1941(A)(3)	NSNP													
HORIZON 2 DEPTH		8-12													
Texture Group	.1941(A)(1)	SCL													
Consistence	.1941	FL													
Structure	.1941(A)(2)	<del>GL</del>													
Mineralogy	.1941(A)(3)	SSP													
HORIZON 3 DEPTH		12-24	12-26	12-26	12-26										
Texture Group	.1941(A)(1)	<del>SL</del>													
Consistence	.1941	S1/2CLM													
Structure	.1941(A)(2)	APL													
Mineralogy	.1941(A)(3)	NSNP													
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942	18	18	18	22										
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RATE	.1955	.2			.2										

NOT ENOUGH SOIL DEPTH  
 IRREGULAR Landscape Features  
 Flood Plain.