

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES										
		1	2	3	4	5	6	7	8	9	10	
LANDSCAPE POSITION	.1940											
SLOPE (%)	.1940											
HORIZON 1 DEPTH		0-18	—————									
Texture Group	.1941(A)(1)	W										
Consistence	.1941											
Structure	.1941(A)(2)											
Mineralogy	.1941(A)(3)											
HORIZON 2 DEPTH		18-34	—————									
Texture Group	.1941(A)(1)	SL										
Consistence	.1941											
Structure	.1941(A)(2)											
Mineralogy	.1941(A)(3)											
HORIZON 3 DEPTH		34-47	—————									
Texture Group	.1941(A)(1)	SL										
Consistence	.1941											
Structure	.1941(A)(2)											
Mineralogy	.1941(A)(3)											
HORIZON 4 DEPTH												
Texture Group	.1941(A)(1)											
Consistence	.1941											
Structure	.1941(A)(2)											
Mineralogy	.1941(A)(3)											
SOIL WETNESS	.1942											
RESTRICTIVE HORIZON	.1944											
SAPROLITE	.1943/.1956											
CLASSIFICATION	.1948											
LONG TERM ACCEPTANCE RATE	.1955	4										

How WA  
 not stated  
 At 107 from  
 Fract P/L  
 I Mark Floor  
 Back to 107

1x20  
 1827



